



# ASSESS DETECT REPORT





# **Assess Summary Report**

Date of Loss January 04, 2021

Claim No. Assess\_Demo\_012

**Property Address** 123 MAIN ST

City, ST 00000

CONTRACTORS CAN INPUT THE DATE OF LOSS FOIZ EACH JOB.

December 31, 2020 Storm Date

Wind Direction NNW

Wind Gust 44 mph

Hail Size STOTEM AND WEATHER DATA IS

> PULLED FIZOM AREA RECORDS BASED ON THE DATE OF LOSS AND

**Decision** POPULATED AUTOMATICALLY.



# **Replace Roof**

More information on the next page

**Summary** 



Summary of findings: Directional hail, most damage on facet P and O. Replace roof. No damage to walls, window screens, personal property, fence.

> CONVENIENT PAGE NUMBERS HELP QUICKLY NAVIGATE TO TZELEVANT SECTIONS.



#### **Contents**


Main Structure Summary	2
Main Roof Images	3
Main Elevation Images	39
Terms and Conditions	52



#### **Main Structure**

No Damage

**Roof Model** 



Decision	Facet
Replace	P, N, O
Repair	

Κ

DECISION SUMMARY BY FACET OFFERS AN AT-A-GLANCE REVIEW TO DETERMINE THE SEVERZITY OF THE DAMAGE.




IMAGETZY OF EACH FACET HELPS CONFITZM DAMAGE DETAILS. BLUE CITZCLES INDICATE CONFITZMED DAMAGE POINTS WITHIN THE GIVEN TEST SQUATZE.



#### **Facet**

aged vents, possibly damaged, replace

WHEN REVIEWING THE DAMAGE,
CONTRACTORS CAN ADD SPECIFIC NOTES,
INCLUDING DETAILS ON SOFT METALS, THAT
WILL POPULATE IN THE FINAL REPORT.










**Test Square** 










# Count 1

DETAILED HIGH-TZESOULTION IMAGETZY SHOWS THE PTZECISE LOCATION OF EACH DETECTED POINT OF DAMAGE FOTZ.
ADDITIONAL VISUAL CONFITZMATION.










Count 2










Count 3










Count 4










Count 5










Count 6










Count 7










Count 8










#### **Annotations**

Full imagery and summaries of each facet are included but not pictured in this sample report.








#### **Left Elevation**



# **Image 1**

no damage to screens

DUTZING A FULL FAGILEVIEW ASSESS INSPECTION, CONTIZACTORS CAN USE THE ASSESS APP TO CAPTURE IMAGERY OF PERSONAL PROPERTY, SOFT METALS, AND PROPERTY ELEVATIONS AND ADD RELEVANT NOTES TO THE REPORT.











Image 2







# **Front Elevation**



Image 1

not damaged










Image 2











Image 3








# **Right Elevation**



Image 1










Image 2

Example note: Downspout not damaged











Image 3

no visible damage to gutter







# **Additional Images**




Image 1










Image 2










Image 3










Image 4











Image 5







# **Terms and Conditions**

© 2008-2020 Eagle View Technologies, Inc. and Pictometry International Corp. – All Rights Reserved – Protected by European Patent Application No. 10162199.3 – Covered by one or more of U.S. Patent Nos. 8,078,436; 8,145,578; 8,170,840; 8,209,152; 8,515,125; 8,825,454; 9,135,737; 8,670,961; 9,514,568; 8,818,770; 8,542,880; 9,244,589; 9,329,749; 9,599,466. Other Patents Pending.